

Technician:

**Greg Felsing** 

## **International Road Dynamics Inc.**

**Site Service Sheet** 

Clear
-------

					System Type: I-SINC				
Date: 10/18/2007	State:	Colorado		Location: I-76 EB Mp 39.7					
Job #: 10785E	Site #:		-	LTPP ID:					
	-		-						
	Lane -	1	Lane -		Lane -		Lane -		
Loops	Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail	
Resistance	0.6	0.7			1				
Leakage	inf	inf							
Inductance	.153mH	.153mH							
Frequency	n/a	n/a							
	Lane - 1		Lane -		Lane -		Lane -		
<u>Weighpads</u>	Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail	
Supply	975.0	975.0							
Signal	840.0	841.0							
Shield	inf	inf							
Zero Pt	.01mV	.01mV							
Serial #	175-7095	175-7094							
<u>Piezos</u>	Lane -		Lane -		Lane -		Lane -		
Amplitude									
Capacitance									
Resistance									
_									
<u>System</u>	Temp Sensor								
A/C Service	124.1VAC				OK				
Power Supply	13.5VDC								
Solar Panel	n/a								
Back-Up	13.5VDC								
System Input		Modem remote accessed by Jim Lynchuk							
Modem Power	11.8VDC	C							
Phone off hook	11.5VDC								
Phone on hook	49VDC								

Date:

10/18/2007